



NABKON

www.nabkon.com

NABKON AUTO SOLUTIONS LTD

1764

Invoice No: 1764

Issue Date: 04/05/2025

PROFORMA INVOICE

Customer's Name: CALLERASIN PLC
 Address: CALLERASIN PLC
 Tel: CALLERASIN PLC

Service Order No: TOYOTA
 Model & Type: RAYA
 License Plate No: SPR 859
 Mileage: AA

Customer's Signature: [Signature]
 Please quote above code for any enquiries
 for NABKON
 Signature: [Signature]

COST
 Cost of parts
 Cost of Labour
 V.A.T.
 Total: 913,500

FRAME No: AA
 ENGINE No: AA

No	Part Name or Work Done	Quality	Cost of Parts	Cost of Labour	Cost of VAT
1	FRONT SHOCK ABSORBERS		110,000 =		
2	REAR SHOCK ABSORBERS		110,000 =		
3	FRONT STABILIZER UNITS		3500 =		
4	FRONT STABILIZER BUSHES		20,000 =		
5	LOWER ARM BUSHES FRONT		80,000 =		
6	FRONT SHOCK PADS		70,000 =		
7	REAR STABILIZER BUSHES		30,000 =		
8	REAR STABILIZER UNITS		3500 =		
9	REAR U-ARMS		90,000 =		
10	REAR LOWER ARM BUSHES		80,000 =		
11	FRONT BAL FOLDS		4500 =		
12	Alignment / Balance		12000 =		
13	CAR WASH		18000 =		
14	FRONT SHOCK PADS		70,000 =		
15	SERVICE CHARGE		98500 =		
Total			<u>913,500</u>		

Total estimate amount (a+b+c)



Suite 11, Dodondawa Piazza 48, Chivita Avenue, Near Chi Ltd., Opp Swimming Pool, Ajao Estate, Lagos-Nigeria

Tel: 08062969629, 08023134264, 07055558032 E-mail: nabkonauto@yahoo.com

AUTO SALES • AUTO BODY CARE • AUTO SPARE PARTS • AUTO INTERIOR CARE • AUTO REPAIRS & SERVICING