



LEASING HOUSE, C & I Leasing Drive, Off Bisola Durosinmi Etti Drive, Off Admiralty Way, Lekki Ph 1, Lagos, Nigeria
+234(0)1 2703700-5, (0)7028185019, (0)7029021757; call centre: (0)70000HERTZ
+234(0)1 2703706
hertz@c-leasing.com

Fleet Maintenance Requisitions Report

#	Branch Office	Vehicle Id	Company	Workshop	Complaint	Maint Status	Verified By	Estimated Cost	Approved Cost
1	port-harcourt	KTU 795 EX	ph airport (replacement)	new salem auto work	A/C NOT COOLING.	requisition created	mbashiru omotayo	54,000.00	28,000.00
2	port-harcourt	FKJ 361 XC	ph airport (replacement)	new salem auto work	ELECTRICAL ISSUE, BRAKE & QUENCH A/C NOT COOLING.	requisition created	mbashiru omotayo	93,000.00	62,000.00
3	port-harcourt	KMC 33 XA	eedc	new salem auto work	-Check and rectify engine unusual noise.	requisition created	mbashiru omotayo	401,000.00	284,000.00
4	port-harcourt	EPE 228 EA	stanbic ibtc	new salem auto work	A/C NOT COOLING	requisition created	mbashiru omotayo	26,000.00	20,000.00
5	port-harcourt	PHC 534 NM	west atlantic shipyard-(was)	new salem auto work	-Check & rectify Noisy front suspension (maybe tie rod noise).	requisition created	mbashiru omotayo	98,000.00	53,000.00
6	port-harcourt	KRD 890 BD	c & i marine	new salem auto work	1. CHECK WATER SHORTAGE 2. TOP GEAR 3.AXLE OIL 4. OIL LEAKAGE AT THE BACK	requisition created	mbashiru omotayo	79,000.00	51,000.00
7	port-harcourt	BDG 637 XL	ge - o & m	new salem auto work	CUT ALTERNATOR & FAN BELT. CHECK ROLLER.	requisition created	mbashiru omotayo	17,000.00	9,000.00
8	port-harcourt	AAA 645 XM	huawei technologies (nig) ltd	new salem auto work	FAULTY POWER STEERING. POWER STEERING LEAKAGE. CHECK HORN.	requisition created	mbashiru omotayo	18,500.00	9,500.00
9	port-harcourt	MUS 920 FS	c&i marine/ c&i petrotech	new salem auto work	1. MISS FIRING 2. LEAKAGE OF AXLE OIL AT BACK RIGHT SIDE 3. FAULTY BACK BUMPER	requisition created	mbashiru omotayo	31,000.00	14,500.00
10	lagos hq	MUS 663 XY	huawei technologies (nig) ltd	new salem auto work	CHECK AND RECTIFY CLUTCH FAULT, & REPLACE ALL THE TRAFICATOR,/BRAKE BULBS.	requisition created	mbashiru omotayo	65,000.00	46,000.00
11	port-harcourt	KJA 78 XC	west atlantic shipyard-(was)	new salem auto work	Check A/C Pulley/Belt	requisition created	mbashiru omotayo	62,500.00	39,000.00
12	port-harcourt	KTU 795 XA	west atlantic shipyard-(was)	new salem auto work	Check Clutch	requisition created	mbashiru omotayo	103,000.00	71,000.00
13	lagos hq	MUS 663 XY	huawei technologies (nig) ltd	new salem auto work	REPLACEMENT OF HOB BEARING [LHS]	requisition created	mbashiru omotayo	53,000.00	31,000.00
14	port-harcourt	AKD 671 FV	hertz open rental port harcourt	new salem auto work	check & rectify fuse.	requisition created	mbashiru omotayo	31,000.00	19,000.00
Total								1,132,000.00	737,000.00

Prepared By: OSENI KADIRI

Approved By: _____