


DRIVERS' INCIDENT REPORT


Nature of Incident	Tyre Puncture
Driver's Name	Nwata Nwankwara
Vehicle Reg. No.	GGH 99 X2
Vehicle Make	Isuzu bus
Incident Date/Time	02-5-2023
Client's Name	Candix
Client's location	Trans Amadi
Location Of Incident	Alhoda
Fine Paid (If Any)	

Driver's Report

Sir on our way to work, I was coming the Candix
 staff to their working site from Alhoda
 around 7:45 am, when I hear air coming out
 from tyre with force. I clear the bus and come
 down all the Candix staff came down, and the tyre
 was down. I remove it and saw that the tyre picked
 metal pin. and I have to grasp it and sent to
 my Supervisor and let her know what happen
 Thank's from

Nwata Nwankwara
 17/5/2023


Signature & Date

 17/5/2023